

**DELHI JAL BOARD: GOVT. OF NCT DELHI**  
**OFFICE OF THE EXECUTIVE ENGINEER (RWH/GWC)**  
**ROOM NO-209, VARUNALAYA PH-I,**  
**JHANDEWALAN NEW DELHI-110005**

No.DJB/EE (RWH/GWC)/2019/373

Dated:- 03/07/19

To,


The Principal  
Pusa Public Sr. Sec. School,  
M-Block, Vikas Puri,  
(Behind DDA Community Centre),  
New Delhi-110018


**Sub:- Adequacy certificate for RWH structure at Pusa Public Sr. Sec. School, M-Block, Vikas Puri, (Behind DDA Community Centre), New Delhi-110018.**

Sir,

Please refer to your letter dated 21.06.2019, in which you have informed that Rain Water Harvesting has been installed at your said premises, the rain water harvesting structure was inspected by NGT joint inspection team on dated 02.07.2019 and found sufficient and adequate to harvest the catchment area of your premises.

You are therefore advised to keep are RWH system neat & clean and maintain the same periodically.

  
Manager  
**PUSA PUBLIC SCHOOL**  
(Recognised & Affiliated to CBSE)  
M-Block, Vikas Puri, New Delhi

  
EE (RWH/GWC)  
EE (RWH/GWC)  
DELHI JAL BOARD  
VARUNALAYA BHAWAN  
JHANDEWALAN, N.D.-5